

| HB | A | B | C | X |
|-------------|----------|----------|----------|----------|
| A MANO | 53 | 48 | 98 | 15 |
| A MANO CZ | 46 | 43 | 98 | 15 |
| CNC | 53 | 48 | 98 | 12 |
| CNC CZ | 46 | 43 | 98 | 12 |
| SPRITZGUSS | 53 | 48 | 98 | 12 |
| HB/2 | A | B | C | X |
| A MANO | 33 | 28 | 98 | 15 |
| A MANO CZ | 27 | 24 | 98 | 15 |
| CNC | 33 | 28 | 98 | 12 |
| CNC CZ | 27 | 24 | 98 | 12 |
| SPRITZGUSS | 33 | 28 | 98 | 12 |

